PATHE NEWS 58/15

FLOOD DAMAGES KARIBA DAM - PHODESIA

F.	G
1	

2-140701

ZE	RO IN	GATE TITLE ENDS AT 31	<u>.0.I</u> .
1	G.V.	ELEVATED SHOT LOOKING DOWN ON THE KARIBA DAM CONSTRUCTION (THIS IS THE TITLE SCENE)	36
2	G. ▼.	FLOOD WATERS RUSHING THROUGH THE PARTLY CONSTRUCTED DAM WALL AND AROUND THE CIRCULAR COFFER DAM	41
3,	L.V.	FLOOD WATER RUSHING THROUGH DAM WALL AT 46 CAMERA PANS TO THE TURBULENT WATER	55
4	G.V.	PAN SHOT THE FLOOD WATERS COMING TOWARDS WITH THE DAM IN THE BACKGROUND	67
5	L.V.	FLOOD WATERS RUSHING THROUGH THE PARTLY MONATRUETING CONSTRUCTED DAM WALL	72
6	G.V.	BRIDGE SPANNING THE RIVER. THE BRIDGE HAS LIFE BELTS HANGING FROM IT ALL THE WAY ALONG, AT 76 CAMERA PANS TO SHOW THE WATER RUSHING AROUND THE BRIDGE PIERS	83
7	L.V.	THE FAST FLOWING WATERS PILING UP ROUND ONE OF THE PIERS	91
8	s.v.	DITTO	98
9	G.V.	ELEVATED SHOT LOOKING DOWN ON THE KARIBA DAM AND AT 106 CAMERA PANS TO SHOW THE BRIDGE SPANNING THE RIVER	117

LENGTH WITH TITLE 94 ft

DAMS 1-9.

34

(b)