

TITLE..... 7'

1. ~~LV workmen repairing and clearing debris from points where~~
accident occurred. 7'
2. ~~TV 41444~~ 5'
3. ~~Angle shot 2 Bourne End signal box.~~ 4'
4. GV pan of wreckage.. and coaches piled up. 7'
5. SV rescue gang, including U.S. troops, ^{police} clearing away debris. 6'
6. LV wreckage and wrecked railway engine embedded in field. 6'
7. GV front of engine embedded in field pan up to wrecked coach
on embankment. 10'
8. GV ~~cranes~~ cranes lifting wrecked coach from debris..to get
injured people out. 6'
9. TV rescue ^{including U.S. troops} gang at work alongside wrecked coach. 6'
10. SV crane ~~man~~ working. 3'
11. LV wrecked coach swinging from crane. 5'
12. STV rescue gang retrieving luggage from wreckage. 5'
13. Shot thru wrecked corridor of coach. 5'
14. LV cranes lifting engine and stretcher party bringing out
dead fireman from wreckage. 8'
15. Elev. shot of wreckage and part of line cleared and train
passing wreckage. 9'

LENGTH WITH TITLE..100ft.

77
84